

Historical Aerial Photography Review

Subject Property

Aerial Photography Timeline

Year	Subject Property	Adjacent Site Descriptions
1937	Unimproved parcel of land with vegetation and cleared land and a wetland/body of water on the bottom left.	<p>N: Roadway followed by unimproved land.</p> <p>NE: Roadway followed by unimproved land.</p> <p>E: Roadway followed by unimproved land.</p> <p>SE: Unimproved land and vegetation.</p> <p>S: Residence and a roadway followed by improved land.</p> <p>SW: Unimproved land.</p> <p>W: Few residences followed by improved land and the rest of the wetland/body of water.</p> <p>NW: Two residences and a roadway followed by unimproved land.</p>
1941	Unimproved parcel of land with vegetation and cleared land and a wetland/body of water on the bottom left.	<p>N: Roadway followed by unimproved land.</p> <p>NE: Roadway followed by unimproved land.</p> <p>E: Roadway followed by unimproved land.</p> <p>SE: Unimproved land and vegetation.</p> <p>S: Residence and a roadway followed by improved land.</p> <p>SW: Unimproved land.</p> <p>W: Few residences followed by improved land and the rest of the wetland/body of water.</p> <p>NW: Two residences and a roadway followed by unimproved land.</p>
1949	Unimproved parcel of land with vegetation and a light road going through the center. A residence is clearly visible on the northeast portion of the subject property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: A couple residential/commercial structures.</p> <p>E: Unimproved land with dense vegetation.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Roadway followed by unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation.</p> <p>W: Body of water surrounded by unimproved land with vegetation.</p> <p>NW: Unimproved land with vegetation.</p>
1951	Unimproved parcel of land with a light road forming a loop and vegetation. A residence is clearly visible on the northeast portion of the subject property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: A couple residential/commercial structures.</p> <p>E: Unimproved land with dense vegetation followed by a light road/trail.</p> <p>SE: Unimproved land with vegetation and scattered trees.</p> <p>S: Roadway followed by unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation and scattered trees.</p> <p>W: Body of water followed by unimproved land with vegetation.</p> <p>NW: Unimproved land with vegetation.</p>
1960	Unimproved parcel of land with vegetation. A road/trail (April Road) is visible going through the subject property on the east side, running north to south.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by agricultural land.</p> <p>E: Unimproved land with dense vegetation.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Light road/trail followed by unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation followed by a roadway.</p> <p>W: Unimproved land with vegetation and a creek.</p> <p>NW: Unimproved land with dense vegetation and a pond.</p>
1966	Unimproved parcel of land with vegetation. A road/trail (April Road) is visible going through the subject property on the east side, running north to south.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Unimproved land with vegetation followed by a roadway.</p> <p>E: Unimproved land with vegetation and a large cleared area.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Light road/trail followed by unimproved land with vegetation.</p> <p>SW: Unimproved land.</p> <p>W: Unimproved land with vegetation and scattered trees.</p> <p>NW: Unimproved land with dense vegetation.</p>

Year	Subject Property	Adjacent Site Descriptions
1973	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by unimproved land with vegetation.</p> <p>E: Unimproved land with vegetation and scattered trees.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Light road/trail followed by unimproved land with vegetation.</p> <p>SW: Unimproved land.</p> <p>W: Unimproved land with vegetation and a small body of water.</p> <p>NW: Small retention pond.</p>
1976	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by unimproved land with some vegetation and a residential structure.</p> <p>E: Unimproved land with scattered trees and vegetation.</p> <p>SE: Unimproved land with vegetation and woodlands.</p> <p>S: Light road/trail followed by unimproved land with vegetation.</p> <p>SW: Unimproved land.</p> <p>W: Unimproved land with vegetation and a pond.</p> <p>NW: Small retention pond.</p>
1980	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by unimproved land with vegetation and another roadway.</p> <p>E: Unimproved land with vegetation, dense woodland, and some residences.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Roadway followed by unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation, scattered trees, and a small pond.</p> <p>W: Unimproved land with vegetation and a small pond.</p> <p>NW: Unimproved land with dense vegetation.</p>
1987	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by unimproved land with vegetation and another small commercial structure.</p> <p>E: Roadway followed by unimproved land with vegetation and a few more residential structures.</p> <p>SE: Unimproved land with vegetation and trees.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation.</p> <p>W: Unimproved land with vegetation, a small pond, and a few more residences.</p> <p>NW: Near the retention pond, a residence followed by roadway and unimproved land.</p>
1994	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by residential structures and unimproved land with vegetation.</p> <p>E: Unimproved land with vegetation and scattered trees followed by woodlands and a small body of water, with an additional residential structure.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation and a small pond.</p> <p>W: Unimproved land with vegetation, light trails, and a pond.</p> <p>NW: Unimproved land with dense vegetation.</p>
1999	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by residential structures and wooded land.</p> <p>NE: Roadway followed by scattered residential structures and vegetation.</p> <p>E: Unimproved land with vegetation and woodlands.</p> <p>SE: Unimproved land with vegetation and small structures.</p> <p>S: Unimproved land with vegetation and open clearings.</p> <p>SW: Unimproved land with vegetation and a body of water.</p> <p>W: Residential structures.</p> <p>NW: Roadway followed by unimproved land and a commercial structure.</p>

Year	Subject Property	Adjacent Site Descriptions
2005	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation and a commercial structure.</p> <p>NE: Roadway followed by unimproved land with vegetation.</p> <p>E: Residential structures and open land with vegetation.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Unimproved land with vegetation followed by a roadway.</p> <p>SW: Unimproved land with vegetation and a cleared field.</p> <p>W: Residential subdivision and a retention pond.</p> <p>NW: Unimproved land with vegetation followed by a roadway.</p>
2006	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by an unimproved parcel of land and a commercial building.</p> <p>NE: Roadway followed by unimproved land with vegetation and residential structures.</p> <p>E: Unimproved land with vegetation and scattered trees.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Unimproved land with vegetation followed by a light road/trail.</p> <p>SW: Unimproved land with vegetation.</p> <p>W: Residential subdivision is constructed.</p> <p>NW: Unimproved land with vegetation.</p>
2007	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Unimproved land with vegetation and a residential structure.</p> <p>NE: Unimproved land with vegetation.</p> <p>E: Unimproved land with vegetation followed by residential structures.</p> <p>SE: Residential structures with a swimming pool and open land.</p> <p>S: Unimproved land with dense vegetation.</p> <p>SW: Unimproved land with vegetation.</p> <p>W: Unimproved land with vegetation.</p> <p>NW: Roadway followed by unimproved land with vegetation.</p>
2010	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Roadway followed by residential structures and vegetation.</p> <p>E: Unimproved land with vegetation and a residential structure.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation and a small pond.</p> <p>W: Unimproved land with vegetation and a pond.</p> <p>NW: Unimproved land with vegetation followed by a residential subdivision.</p>
2013	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Residential property with a swimming pool and open fields.</p> <p>E: Unimproved land with vegetation and scattered residential structures.</p> <p>SE: Unimproved land with vegetation and a pond.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation and a small pond.</p> <p>W: Unimproved land with dense vegetation and a small pond.</p> <p>NW: Residential subdivision with single-family homes and a retention pond.</p>
2015	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Commercial structure with parking lot and unimproved land followed by a roadway.</p> <p>NE: Unimproved land with vegetation.</p> <p>E: Unimproved land with vegetation.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation.</p> <p>W: Cemetery being built.</p> <p>NW: Roadway followed by unimproved land with vegetation.</p>
2017	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Residential structures and a large grassy field followed by a roadway.</p> <p>E: Unimproved land with dense vegetation.</p> <p>SE: Unimproved land with vegetation.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Unimproved land with vegetation followed by a cleared area and a roadway.</p> <p>W: Cemetery is built and there's also still the residential subdivision there.</p> <p>NW: Unimproved land with vegetation followed by residential structures.</p>

Year	Subject Property	Adjacent Site Descriptions
2019	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by a commercial structure with a parking lot and unimproved land with vegetation.</p> <p>NE: Roadway followed by unimproved land with vegetation.</p> <p>E: Unimproved land with vegetation followed by residential structures.</p> <p>SE: Residential structures and maintained land with scattered trees.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Roadway followed by unimproved land with vegetation.</p> <p>W: Roadway followed by manicured open land with scattered trees and paved paths.</p> <p>NW: Roadway followed by a commercial structure.</p>
2021	Unimproved parcel of land with vegetation and April Road on the east side of the property.	<p>N: Roadway followed by unimproved land with vegetation.</p> <p>NE: Residential structures with a pool and a large grassy field.</p> <p>E: Scattered residential structures and unimproved land with vegetation.</p> <p>SE: Unimproved land with vegetation and a residential structure.</p> <p>S: Unimproved land with vegetation.</p> <p>SW: Golf course with a winding paved path and trees.</p> <p>W: Unimproved land with vegetation followed by a commercial structure, parking lot, and roadway.</p> <p>NW: Roadway followed by a park.</p>
2023	Unimproved parcel of land with vegetation and light roads/trails.	<p>N: Unimproved land with vegetation.</p> <p>NE: Roadway followed by scattered residential structures and unimproved land with vegetation.</p> <p>E: Unimproved land with vegetation.</p> <p>SE: Unimproved land with vegetation and dense trees.</p> <p>S: Unimproved land with dense vegetation.</p> <p>SW: Unimproved land with vegetation followed by a commercial structure and parking lot.</p> <p>W: Residential subdivision.</p> <p>NW: Residential subdivision followed by a roadway and a commercial structure with unimproved land.</p>

Source: Historical Aerial Photography. Analysis performed using AI-assisted image interpretation.